

### Survey of Housing Conditions

This section provides information on Vance County's structural conditions. The material presented in this section has been gathered from the United States 1970 Census Count and the Structural Quality Survey. The condition, total number and occupancy of the dwelling units was furnished by the housing quality data. The number of owner/renter occupied dwelling units was acquired by applying an owner/renter percentage factor provided by township from the census information against the housing quality data. The results of this survey and data application is provided in the following section.

Prior to this information, a brief definition of the terms which will be used in the following section is presented below.

Standard - refers to those housing units with no or only slight structural defects as defined in the previous section on structural quality.

Substandard - refers to those housing units which were determined to be in a deteriorated or in a delapidated condition via the Structural Quality Survey.

Suitable for Rehabilitation - refers to those housing units which were found to be in a deteriorating condition only, which meant that they were not in a state of disrepair.

Owner Occupied - are those housing units which are inhabited by